## LEON PIERCE BODY REPAIRS, INC. 521 N. PORTER

NORMAN, OK 73071

PHONE: (405)364-2799 FAX: (405)364-1272

## \*\*\* PRELIMINARY ESTIMATE \*\*\*

02/14/2019 12:01 PM

Owner

Owner: Cory Averitt

Inspection

Inspection Date: 02/14/2019 11:59 AM

Appraiser Name: Steve Ehardt

Address:

Email: office@leonpierce.com

Inspection Type:

Appraiser License #:

Work/Day: (405)364-2799

Repairer

Repairer: Leon Pierce Body Repair

Address: 521 N. Porter

City State Zip: Norman, OK 73071

Email: office@leonpierce.com

Contact:

**Work/Day:** (405)364-2799 **FAX:** (405)364-1272

Target Complete Date/Time:

Days To Repair: 7

Vehicle

OEM Part Price Quote ID: \*\*\*\*

2008 Pontiac G6 GT 2 DR Coupe 6cyl Gasoline 3.5 4 Speed Automatic

> Lic Expire: Veh Insp# : Condition:

Ext. Refinish: Two-Stage

VIN: 1G2ZH17NX84164677

Mileage Type: Actual Code: W3513C

Int. Refinish:

**Options** 

AM/FM CD Player Anti-Lock Brakes Chromed Alloy Wheels Fog Lights

Keyless Entry System Monsoon Sound System Power Door Locks Power Windows Side Airbags Tachometer

Side Airbags
Tachometer
Tilt Steering Wheel
Trip Computer

Air Conditioning Bucket Seats Cruise Control Head Airbags Leather Steering Wheel

OnStar System
Power Mirrors
Rear Window Defroster
Sport Suspension

Telescopic Steering Whl Tinted Glass Velour/Cloth Seats Alarm System
Center Console
Dual Airbags
Intermittent Wipers
Lighted Entry System
Power Brakes
Power Steering

Rem Trunk-L/Gate Release Strg Wheel Radio Control Theft Deterrent System Traction Control System XM Satellite Radio

Damages						work of the recommendant of the rest of the recommendant		-
Line Op	Guide	MC Description	n	MFR.Part No.	Price	ADJ% B%	Hours	F
ront Bump	<u>er</u>							
1 E 2 L	6 6	Cover,Fron 13 Cover,Fron		19151158 GM Part Refinish 2.8 Surface 0.6 Two-stage setup	\$293.68		4.2 4.0	SM RF
2	4000	D 151D	0	0.6 Two-stage	11.10			0.
3	1023	Ret,Frt Bun Quantity of	nper Cover 2 @ INC each	Replace OEM	INC			SN
4 E	11	·	t Bmpr Cover	22689321 GM Part	\$97.85		0.2	SN
5 TE	102	02 Grille,Frt Br		Partial Replace Price	\$320.00			SN
6 E	174	Grille,Frt Br		15243286 GM Part	\$61.27		INC	SN
7 E	175	Grille,Frt Br	mpr Cvr RT	15243287 GM Part	\$61.27		INC	SI
8 ET	465	Grille,Frt Br	mpr Cvr LT	Partial Replace Labor			INC	SN
9 ET	466	Grille,Frt Br	mpr Cvr RT	Partial Replace Labor			INC	SN
10 E	62	Defl, Front E	Bumper	25995473 GM Part	\$115.45		0.1	SN
11 E	76		mpr License	10379556 GM Part	\$45.97		0.2	SI
12 E	50		ront Bumper	20830367 GM Part	\$158.33		INC	SI
13 E	19		Bumper Mtg	15234066 GM Part	\$58.07		INC	SN
14 E	172	Moulding,G		15221711 GM Part	\$36.85		INC	SN
15 E	173	Moulding,G		15221711 GM Part	\$36.85		INC	SI
ront End P	anel An	d Lamps						
16 E	41		Assy, Halogen LT	20821143 GM Part	\$175.00		INC	SI
17 E	42		Assy, Halogen RT	20821144 GM Part	\$175.00		INC	SN
18 N	973	Headlamps		Additional Labor	\$175.00		0.4	SN
ont Body	And Wii	ndshield						
19	83	Panel, Hood	I	Repair			4.0*	SN
20 L	83	Panel, Hood		Refinish 2.9 Surface 0.6 Two-stage	- d		4.0	RI
04 DI	4000			0.5 Feather, Prime & Blo	OCK		0.4	
21 RI	1039	,	Washer LT	R & I Assembly			0.1	SN
22 RI	1040	Nozzle, W/S Washer RT		R & I Assembly			0.1	SN
23 RI	86	Pad, Insulate		R & I Assembly			0.3	SN
24 BR	103	Fender, Fror	nt LT	Blend Refinish 0.6 Blend			0.9	RF
	40.4		. ==	0.3 Two-stage				
25 I	104	Fender, Fror		Repair			0.5*	SN
26 L	104	Fender,Fror	nt R I	Refinish 1.4 Surface 0.3 Two-stage			1.7	RF
anual Entr	<u>ies</u>							
27 SB		HAZARD. V	VSTE. REM.	Sublet Repair	\$5.00*			SM
28 I		MASK FOR	<b>OVERSPRAY</b>	Sublet Repair	\$5.00*			SM
28 I	tems							
		MC	Message					
		02	PART NO. D	ISCONTINUED, CALL DEALE	ER FOR EXACT PART	NO.		
		13		.6 HOURS FIRST PANEL TV				
Estimate 1	otal & E	ntries	the Control of the Co				V. 4840 107 10 10404	
ross Parts					\$1,635.59			Comment of the control
aint & Mate	erials		10.1 I	Hours @ \$42.00	\$424.20			

Feather Prime & Block Material Parts & Material Total Tax on Parts & Material	ials	0.5 Ho	urs @ \$4 @ 8.	42.00 750%	\$21.00	\$2,080.79 \$182.07
Labor	Rate	Replace Re Hrs	pair Hrs	Total Hrs		
Sheet Metal (SM) Mech/Elec (ME)	\$53.00 \$98.00 \$70.00	5.2	4.9	10.1	\$535.30	
Frame (FR) Refinish (RF)	\$53.00	10.6		10.6	\$561.80	
Labor Total Sublet Repairs				20.7 Ho	ours \$10.00	\$1,097.10
Gross Total Net Total					\$ 10.00	\$3,369.96 \$3,369.96

Alternate Parts No
OEM Part Prices DT 02/14/2019 12:01 PM EstimateID 525372116275568640 QuoteID \*\*\*\*
SPPL Yes Zip Code: 73026 Default
Rate Name Default

Audatex Estimating 8.0.642 Update 3 ES 02/14/2019 12:05 PM REL 8.0.642 Update 3 DT 02/01/2019 DB 02/08/2019 © 2019 Audatex North America, Inc.

0.5 HOURS OF REPAIR TIME WERE ALLOCATED TO FEATHER, PRIME & BLOCK AS INDICATED BY THE ESTIMATE PREPARER'S LABOR ITEMIZATION. FEATHER, PRIME & BLOCK LABOR IS REFLECTED UNDER THE REFINISH OPERATION FOR THE APPLICABLE DAMAGE ENTRY.

2.4 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.

## Op Codes

* = User-Entered Value	^ = Labor Matches System Assigned Rates	E = Replace OEM
NG = Replace NAGS	EC = Replace Economy	OE = Replace PXN OE Srpls
UE = Replace OE Surplus	ET = Partial Replace Labor	EP = Replace PXN
EU = Replace Recycled	TE = Partial Replace Price	PM= Replace PXN Reman/Reblt
UM= Replace Reman/Rebuilt	L = Refinish	PC = Replace PXN Reconditioned
UC = Replace Reconditioned	TT = Two-Tone	SB = Sublet Repair
N = Additional Labor	BR = Blend Refinish	I = Repair
IT = Partial Repair	CG= Chipguard	RI = R & I Assembly
P = Check	AA = Appearance Allowance	RP = Related Prior Damage