

X

< 01/13/2021 ~

All Day ~

All Payment Methods >

Export >

All Types ~

Complete ~

Card # v

Filter by card (last 4)

Jan. 13, 2021

1

COMPLETE TRANSACTION

\$10,343.75

TOTAL COLLECTED

\$10,343.75

NET SALES

Wednesday, January 13, 2021

\$10,343.75

3:24 pm

Custom Amount Mills Body Shop

\$10,343.75



MILLS BODY SHOP

Workfile ID: PartsShare:

Estimator:

Create Date:

6cf8db9d 63KKXM

Federal ID:

450465113

Garold Mills

11/19/2020

INVOICE Cosmetic Collision Care
1527 24TH AVE SW, millsbody@aol.com, NORMAN,

OK 73072 Phone: (405) 321-4100

FAX: (405) 321-4106

Final Bill

RO Number: 1757

Customer:

Insurance:

Adjuster:

1

Phone: Claim:

Loss Date:

(405) 517-6100

Schooler, Green

Deductible:

2016 FORD Mustang Fastback 2D CPE 6-3.7L Gasoline Sequential MPI

VIN:

1FA6P8AM0G5232039

Interior Color: Exterior Color: Mileage In:

Vehicle Out:

License: State:

OK

Production Date:

Mileage Out: Condition:

Excellent

Job #:

Line	Ver	Operation	Description	Qty	Extended Price \$	Part Type	Labor	Туре	Paint
L	E01	Repair	OEM Pre/ Post Computer Scan			OEM	1.2	Mech	
2	E01		FRONT BUMPER & GRILLE				1000 March		
3	E01	Remove/Replace	O/H front bumper				3.0	Body	
1	S01	Remove/Replace	Valance panel	1	260.62T	Non OEM	0.0	Body	
5	E01	Remove/Replace	Bumper cover w/o tow hook	1	241.00T	Non OEM	0.0	Body	3.3
5	E01		Add for Three Stage						2.3
,	E01		Add for fog lamps						
3	S01	Remove/Replace	RT Side support w/o fog lamps	1	38.05T	OEM	0.0	G 348	
9	S01	Remove/Replace	RT Support bracket	1	18.18T	OEM	0.0	Body	
.0	E01	Refinish	Tow eye cap						0.2
11	E01		Add for Three Stage						0.1
12	E01		FRONT LAMPS						
13	S01	Remove/Replace	RT Headlamp assy	1	1,000.00T	Non OEM	0.5	0 17 600 000 000 000 000 000 000 000 000 00	
14	S01	Remove/Replace	RT Park lamp	1	87.48T	Non OEM	0.0		
15	S01	Remove/Replace	LT Headlamp assy	1	800.00T	RCY	0.5	Body	
16	S01	Remove/Replace	LT Marker lamp bulb socket	1	11.85T	OEM			
17	501	Remove/Replace	LT Marker lamp bulb socket	1	11.85T	OEM			
18	E01		RADIATOR SUPPORT						
19	S01	Remove/Replace	Under cover	1	294.27T	Non OEM	0.0	5 STATE OF THE STA	
20	S01	Remove/Replace	RT Air deflector w/o adaptive cruise	1	51.80T	OEM	0.1		
21	S01	Remove/Replace	RT Mount bracket	1	16.48T	OEM	0.6	5 Body	0.
22	E01	200 € 1 200 000 000 000 000 000 000 000 000 0	Add for Three Stage						0.
23	E01		FENDER						

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

RO Number: 1757

2016 FORD Mustang Fastback 2D CPE 6-3.7L Gasoline Sequential MPI

2016 F	ORD Mu	stang Fastback 2D CPE	6-3.7L Gasoline Sequential MPI						
24	E01	Remove/Replace	RT Fender V6, ECOBOOST, ECOBOOST PREMIUM (ALU)	1	369.00T	Non OEM	2.4	Body	2.2
25	E01		Add for Three Stage						1.5
26	E01		Add for Edging						0.5
27	E01	Remove/Replace	Deduct for Overlap				(0.3)	Body	
28	E01	Remove/Replace	RT Front bracket	1	13.00T	Non OEM	0.1	Body	
29	S01	Remove/Replace	LT Fender liner w/o SHELBY w/insulator	1	71.50T	Non OEM	0.3	Body	
29	301		pkg				2.0	Body	0.6
30	E01	Repair	RT Upper rail				2.0	body	0.0
31	E01		WHEELS				0.1	Mech	
32	E01	Remove/Install	RT/Front R&I wheel				0,1	Piech	
33	E01		FRONT SUSPENSION				4.1	Mech	
34	E01	Remove/Replace	O/H frt susp rt						
35	E01	Remove/Replace	RT Knuckle	1	299.75T	OEM	0.0	Mech	
36	E01	Remove/Replace	RT Ft lwr cntl arm w/o performance pkg.	1	145.18T	OEM		Mech	
37	E01	Remove/Replace	Wheel alignment align four wheels					Mech	
38	E01	Remove/Replace	Deduct for Overlap				0.0	Mech	
39	E01	Remove/Replace	RT Ft lwr cntl arm bolt	1	6.50T	OEM			
40	E01	Remove/Replace	RT Rr lwr cntl arm w/o performance pkg.	1	265.98T	OEM		Body	
41	E01	Remove/Replace	Deduct for Overlap					Body	
42	E01	Remove/Replace	RT Strut coupe, w/o 20" wheels, w/o BULLITT 3.7 liter	1	188.71T	OEM	0.0	Body	
43	E01	Remove/Replace	Deduct for Overlap				0.0	Body	
44	E01		DOOR						
45	E01	Blend	RT Door shell						1.5
46	E01	Remove/Install	RT Belt w'strip black				0.3	Body	
47	E01	Remove/Install	LT Front molding				0.1	Body	
48	E01	Remove/Install	LT R&I mirror				0.3	Body	
49	E01	Remove/Install	RT Handle, outside primed				0.5	Body	
50	E01	Remove/Install	RT R&I trim panel				0.5	Body	
51	E01	Remove/Install	RT Water shield front				0.1	Body	
52	E01	Remove/Insum	Clean for delivery/post-repair cleaning Covid 19	1	15.00T	Non OEM	0.5	Body	
F-2	E01	Remove/Replace	Clips/retainers	1	28.00T	Non OEM			
53		Remove/Replace	Cover Car 25' x 8.50 25% Markup \$5.00	1	10.00T	Non OEM	0.3	Body	
54	E01	Remove/Replace	Tape						
55	E01	Remove/Replace	Flex additive	1	5.00T	Non OEM			
56	E01	Remove/Replace	Hazardous waste removal	1	5.00	Other			0.4
57	E01	Remove/Replace	Nib and Polish			Non OEM			0.4
58	E01	Remove/Replace	Rustproofing	1	8.00T			2 Body	
59	E01		Pull Rt frt rail			Non OEM		Body	
60	E01		Battery Support Pre/Post				0.	5 Mech	
61	E01	(5)	Towing	1	441.53	Other			
62	S01		RESTRAINT SYSTEMS						
02	301								

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

RO I	Numb	er: 1757						
2016	FORD M	ustang Fastback 2D CPI	E 6-3.7L Gasoline Sequential MPI					
63	S01	Remove/Replace	Clockspring	1	198.43T	OEM		1050
64	S01	Remove/Replace	Air bag disable SRS system				1.0	Body
65	S01	Remove/Replace	Air bag system diagnosis ck system operation				0.5	Body
66	S01	Remove/Replace	Control module	1	516.57T	OEM	0.4	Body
67	S01	Remove/Replace	LT Knee air bag	1	338.03T	OEM	0.4	Body
68	S01	Remove/Replace	Ft impact sensor	1	149.23T	OEM	0.3	Body
69	S01	Remove/Replace	LT Seat belt assy	1	403.78T	OEM	0.6	Body
70	S01	Remove/Replace	LT Buckle	1	96.10T	OEM	0.1	Body
71	S01		WINDSHIELD					
72	S01	Remove/Replace	Washer reservoir w/o SHELBY	1	46.00T	Non OEM	0.3	Body
73	S01		PILLARS, ROCKER & FLOOR					
74	S01	Remove/Replace	RT Rocker molding pin	22	55.00T	OEM		
75	501	100 TO 10	Bracket	1	15.52T	Non OEM		
76	S01	Remove/Replace	Labor Modules scan and repair	1	90.00T	Other		

Estimate Totals	Discount \$	Markup \$	Rate \$	Total Hours	Total \$
Parts		200.00			6,370.86
					441.53
Sublet/Miscellaneous			52.00	18.7	972.40
Labor, Body			52.00	12.9	670.80
Labor, Refinish			100.00	7.7	770.00
Labor, Mechanical			100.00	717	516.00
Material, Paint					9,741.59
Subtotal					9,741.39
Sales Tax					602.16
	- pyria a fire of the same of				10,343.75
Grand Total					
Net Total					10,343.75

	10,343.75
Net Total	

Estimate Version	Total \$
Original	6,934.84
Supplement S01	3,408.91
Insurance Total \$:	10,343.75
Received from Insurance \$:	0.00
Balance due from Insurance \$:	10,343.75
Customer Total \$:	0.00
Received from Customer \$:	0.00
Balance due from Customer \$:	0.00

Thank you for letting us repair your vehicle!

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural