

Hiller Separation & Process LLC

1010 Mclean Street
Lampasas, TX 76550

Phone # 512-556-5707 sheila.pickel@hiller-us.com
Fax # 512-556-8597 www.hiller-us.com

Date	Quotation #
4/28/2015	Q15-1429

Bill To:
City of Norman WWTP PO Box 370 Norman, OK 73070 Attn: Accounts Payable

Ship To:
City of Norman WWTP 3500 South Jenkins Avenue Norman, OK 73070 Attn: Ryan Bart

Terms of Payment	Customer's PO No.	Project Name	Serial No.
Net 30			JS00164 & JS00165

Item	Description	Qty	Price	Total
	Rebuild Services for JS00164 - Hiller Centrifuge			
	Parts replaced on Scroll:			
Z11-0643	RADIAL SHAFT SEAL	1	597.05	597.05
Z11-0642	RADIAL SHAFT SEAL	1	781.86	781.86
Z18-0111	Roller Bearing	1	666.39	666.39
Z24-0003	DOWELL PIN (DP54)	1	25.58	25.58
Z11-0033	"V"-Ring	1	80.24	80.24
Z11-0482	ROUND SEAL PACKING (RING)	1	10.43	10.43
	Parts replaced on Bowl:			
Z18-0077	Roller Bearing	1	910.90	910.90
N5419-0010	FELT RING	1	11.06	11.06
Z11-0126	O-RING	1	8.37	8.37
Z11-0066	O-RING	2	3.625	7.25
Z11-0056	O-RING	2	1.90	3.80
DP540001-04-58	RING	1	597.21	597.21
DP540001-04-59	RING (DP54)	1	561.35	561.35
Z18-0072	ROLLING BEARING	1	639.70	639.70
Z11-0025	ROUND SEAL PACKING (RING)	1	12.32	12.32
N5419-0004	FELT STRIP (DP45)	2	4.11	8.22
N5419-0001	FELT STRIPS	1	4.11	4.11
Z13-00412X01	Planetary Gear (including shell, grease quantity adjust, main bearing and cam ring)	1	21,792.50	21,792.50
Service Tech.	Service Technician (Disassemble and inspect rotating assembly; remove carpet from bowl; clean and replace necessary spare parts; reassemble assembly)	1	7,500.00	7,500.00
Freight	Line Haul of assembly - round trip (estimated)	1	2,500.00	2,500.00

Total**\$36,718.34**

Please make check payable to: Hiller Separation & Process, LLC