

February 6, 2017

Mr. Ken Danner Subdivision Development Manager City of Norman 201–A West Gray Street Norman, OK 73069

Re:

Plat Correction

Eastpark Crossing Section II

Dear Mr. Danner,

The Eastpark Crossing Section II recorded Final Plat contains a scrivener's error that I wish to correct. The error is in the stated bearing on the north boundary of Lot 1, Block 1. The error is contained in both the written legal description and as shown on the north boundary of Lot 1, Block 1. The stated bearing reads South 89°59'05" East, and should be corrected to read **North** 89°59'05" East.

Please review the attached plat correction documents and submit to the Norman City Council for approval. Please send me a file stamped approved document once it has been filed with the Cleveland County Clerk. Please call if you need any additional information or have any questions. Thank you.

Sincerely,

Bryan E. Coon, P.L.S.

Huitt-Zollars, Inc.