## Angelo,

At your request I contacted Robert and informed him what we could offer for assistance to Moore. Below is a list of 6 Econolite ASC/2 traffic signal controllers that the City of Norman will no longer use due to our recent upgrades requiring the Econolite ASC/3 traffic signal controller.

Manufacturer

Econolite

Model

ASC/2-2000

Part Number

32800G2

Serial Number

599

Program Number

32790C8000BU1

Manufacturer

Econolite

Model

ASC/2-2000

Part Number

32800G2

Serial Number

2629

Program Number

32791C8061U1

Manufacturer

Econolite

Model

ASC/2-2000

Part Number

32800G2

Serial Number

1732

Program Number

32790C8061U1

Manufacturer

Econolite

Model

ASC/2-2100

Part Number

32800G3

Serial Number

7611

Program Number

32790C8000BU1

Manufacturer

Econolite

Model

ASC/2-2100

Part Number

32800G3

Serial Number

7610

Program Number

32790C8000BU1

Manufacturer

Econolite

Model

ASC/2-2100

Part Number Serial Number 32800G3 1983

Program Number

32790C8000BU1

Brian McNabb

City of Norman, OK Traffic Signal Supervisor

C-405-213-5333

P-405-329-0528

F-405-292-9765