



MILLS BODY SHOP

Workfile ID: 54efbd57
Federal ID: 450465113

INVOICE Cosmetic Collision Care
1527 24TH AVE SW, millsbody@aol.com,
NORMAN, OK 73072
Phone: (405) 321-4100
FAX: (405) 321-4106

Preliminary Estimate

Customer: Ballard, Melody

Insured: Ballard, Melody
Type of Loss:
Point of Impact: 03 Right T-Bone (Right Side)

Policy #:
Date of Loss:

Claim #:
Days to Repair: 0

Owner:

Ballard, Melody
(601) 201-4814 Business

Inspection Location:

MILLS BODY SHOP
1527 24TH AVE SW
millsbody@aol.com
NORMAN, OK 73072
Repair Facility
(405) 321-4100 Business

Insurance Company:

Norman Police Department

VEHICLE

Year: 2006	Body Style: 4D SED	VIN: 1FAPF53U36A224633	Mileage In:
Make: FORD	Engine: 6-3.0L-FI	License:	Mileage Out:
Model: TAURUS SE	Production Date:	State:	Vehicle Out:
Color: Gold Met Int:	Condition: Fair	Job #:	

TRANSMISSION

Automatic Transmission
Overdrive

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors

DECOR

Dual Mirrors
Body Side Moldings
Console/Storage

CONVENIENCE

Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control

Rear Defogger
Keyless Entry

RADIO

AM Radio
FM Radio
Stereo
Search/Seek
Cassette
SAFETY

Drivers Side Air Bag
Passenger Air Bag

SEATS

Cloth Seats

WHEELS

Wheel Covers

PAINT

Clear Coat Paint

Preliminary Estimate

Customer: Ballard, Melody

Vehicle: 2006 FORD TAURUS SE 4D SED 6-3.0L-FI Gold Met

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	#	Frame/Unibody Repair & Set up		1	220.00 X		
2	REAR DOOR						
3	*	Repl LKQ RT door assy +25%	2F1Z5424630AA	1	<u>181.25</u>	<u>5.0</u>	3.2
4		Add for Clear Coat					1.3
5	~	Clean or recondition parts or assemblies				<u>4.0</u>	
6	~	Trial fit for alignment (during and after pulls)				<u>1.0</u>	
7	FRONT BUMPER						
8	*	R&I Bumper cover				<u>2.3</u>	
9	FRONT LAMPS						
10		R&I RT Headlamp assy all				<u>0.4</u>	
11	FENDER						
12	**	Repl Non OEM CAPA RT Fender	YF1Z16005AA	1	178.00	3.0	1.8
13		Overlap Major Adj. Panel					-0.4
14		Add for Clear Coat					0.3
15		Add for Edging					0.5
16		Add for Clear Coat					0.1
17	FRONT DOOR						
18	*	Repl LKQ RT door assy +25%	1F1Z5420124AA	1	<u>312.50</u>	<u>5.0</u>	3.2
19		Overlap Major Adj. Panel					-0.4
20		Add for Clear Coat					0.6
21	#	Rpr Clean up Lkq part				3.0	
22	*	Repl LKQ RT Mirror w/o heated glass w/o lamp +25%	6F1Z17682C	1	<u>43.75</u>	<u>0.4</u>	<u>0.6</u>
23	REAR LAMPS						
24		R&I RT Tail lamp assy				<u>0.4</u>	
25	QUARTER PANEL						
26	*	Rpr RT Quarter panel				<u>8.0</u>	2.2
27		Overlap Major Adj. Panel					-0.4
28	*	Add for Clear Coat					0.4
29	REAR BUMPER						
30		R&I Bumper cover				1.6	
31	**	Refn Non OEM Cover Car					0.2
32	**	Non OEM Clean up broken glass		1			
33	**	Refn Non OEM Color tint / color match					0.2
34	**	Refn Non OEM Corrosion protection primer					0.2
35	**	Rpr Non OEM Feather edge prime and block					
36	#	Repl Hazardous waste removal		1	3.00		
37	FRONT SUSPENSION						
38		Repl Wheel alignment align four wheels		1	m	2.8	

Preliminary Estimate

Customer: Ballard, Melody

Vehicle: 2006 FORD TAURUS SE 4D SED 6-3.0L-FI Gold Met

39		OTHER CHARGES			
40	#	Rope Glass	1	10.00	
		SUBTOTALS		948.50	36.9
					13.6

ESTIMATE TOTALS

Category	Basis		Rate	Cost \$
Parts				718.50
Body Labor	36.9 hrs	@	\$ 46.00 /hr	1,697.40
Paint Labor	13.6 hrs	@	\$ 46.00 /hr	625.60
Paint Supplies	13.6 hrs	@	\$ 36.00 /hr	489.60
Miscellaneous				220.00
Other Charges				10.00
Subtotal				3,761.10
Sales Tax	\$ 1,218.10	@	8.2500 %	100.49
Grand Total				3,861.59
Deductible				0.00
CUSTOMER PAY				0.00
INSURANCE PAY				3,861.59

Thanks for allowing us to provide you with an "estimate" for your repairs. The estimate provided should be all of the labor and materials necessary to repair your vehicle. In writing the "estimate" we try to include all "visible" items necessary to complete the repairs according to the original standards set by the manufacturer of your vehicle. Some damaged areas or procedures may be missed in writing the estimate. In addition other parts or labor items maybe discovered after the car repairs are under way. If however, any unforeseen items are discovered during the repair process we will contact the insurance company and/or you to explain the circumstance. Manufacturers often change prices without notification and may change the estimate totals. This "estimate" does not constitute a one party contract. Please be assured that most repairs are completed without changes to the original "estimate." It is our desire to make a lifelong customer. Additional repairs added to the repair require increase in the Final Bill. Anything not on the estimate is additional.

Our Technicians are ASE and ICAR trained to provide excellent repairs to our customers. We use the highest quality materials, professional technicians and quality equipment to complete your repairs according to those standards. No sub-standard parts are used in our repairs. If you have any questions please feel free to come by or call us.

Any Vehicle left after the vehicle has been repaired longer than 5 working days will accrue storage fees of 20 dollars per day from the date the repairs were completed. These fees can be set aside with notice between the vehicle owner and the shop manager. Please let us know if you need us to keep your vehicle longer than the repairs will take. Any vehicle left longer than 30 days without approval can be disposed of as the shop deems fit. Thanks for your cooperation.

Any Person who knowingly, and with intent to injure, defraud or deceive any Insurer, makes any claim for the proceeds of an insurance policy containing any false, incomplete or misleading information is guilty of a felony.