

CITY OF NORMAN
POST OFFICE BOX 370
NORMAN, OKLAHOMA 73070

FILED IN THE OFFICE
OF THE CITY CLERK
ON 5-27-14

NOTICE OF TORT CLAIM

CLAIMANT: Natalie Carns DATE: 5/23/14

ADDRESS: 11817 Leaning Elm CITY: OKC

STATE: OK ZIP: 73120 PHONE: (H) 816-9472 (W) 364-3703

DATE OF INCIDENT: 5/22/14

LOCATION OF INCIDENT: Sarkeys Foundation - 530 E. Main St.

STATEMENT OF CIRCUMSTANCES / REASONS YOU BELIEVE CITY IS LIABLE:

My car was parked at Sarkeys Foundation parking lot.
A City vehicle drove through and hit driver side corner
and driver side mirror.

* I will be using the Enterprise in Norman that the
city has a direct pay with while my car is fixed.

(use additional pages if necessary)

MONETARY STATEMENT: List of expenses claimed for payment:

<u>Service King</u>	<u>\$ 2,371.50</u>	<u>\$</u>
<u></u>	<u>\$</u>	<u>\$</u>
<u></u>	<u>\$</u>	<u>\$</u>

TOTAL AMOUNT CLAIMED: \$

NAME AND ADDRESS OF INSURANCE COMPANY: Safeco
3232 W. Britton Rd, 150 OKC AGENT: Ryan Stoner

THIS FORM MUST BE SIGNED AND RETURNED WITH ALL REQUESTED INFORMATION IN ORDER TO BE PROCESSED

I SWEAR AND/OR AFFIRM THE INFORMATION PROVIDED ABOVE IS TRUE AND CORRECT.

Natalie Carns
CLAIMANT'S SIGNATURE



SERVICE KING #29 NORTH OKC

Workfile ID: f063d5fb
Federal ID: 75-1781281

To schedule repairs please call
1-866-730-KING (5464)
420 W JOHN KILPATRICK TPKE, OKLAHOMA CITY,
OK 73114
Phone: (405) 749-9990
FAX: (405) 749-7816

Preliminary Estimate

Customer: Carns, Natalie

Job Number:

Written By: Tyler Emery

Insured: Carns, Natalie
Type of Loss:
Point of Impact: 06 Rear

Policy #:
Date of Loss:

Claim #:
Days to Repair: 8-14

Owner:
Carns, Natalie
(405) 818-9472 Business

Inspection Location:
SERVICE KING #29 NORTH OKC
420 W JOHN KILPATRICK TPKE
OKLAHOMA CITY, OK 73114
Repair Facility
(405) 749-9990 Business

Insurance Company:
CUSTOMER PAY

VEHICLE

Year: 2012 Body Style: 4D SED VIN: 5NPEB4AC6CH422331 Mileage In: 50939
Make: HYUN Engine: 4-2.4L-FI License: 110KDM Mileage Out:
Model: SONATA GLS Production Date: 11/2011 State: Vehicle Out:
Color: red Int: Condition: Good Job #:

TRANSMISSION

Overdrive
6 Speed Transmission

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Heated Mirrors

DECOR

Dual Mirrors
Tinted Glass

Console/Storage

CONVENIENCE

Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Alarm
Steering Wheel Touch Controls
Telescopic Wheel

RADIO

AM Radio

FM Radio

Stereo

CD Player

Auxiliary Audio Connection

Satellite Radio

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Front Side Impact Air Bags
Head/Curtain Air Bags
Communications System

Hands Free Device

SEATS

Cloth Seats
Bucket Seats

WHEELS

Wheel Covers

PAINT

Clear Coat Paint

OTHER

Traction Control
Stability Control
Power Trunk/Gate Release

Preliminary Estimate

Customer: Carns, Natalie

Job Number:

Vehicle: 2012 HYUN SONATA GLS 4D SED 4-2.4L-FI red

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		FENDER					
2	R&I	LT Trim molding				0.2	
3		ROOF					
4	R&I	LT Roof molding				0.5	
5	#	Refn clear over left roof rail					0.8
6	#	rope back glass left side		1		0.3	
7		PILLARS, ROCKER & FLOOR					
8	R&I	LT Rocker molding				0.9	
9	R&I	LT Pillar molding				0.3	
10		FRONT DOOR					
11	R&I	RT Mirror assy w/o turn signal				0.3	
12	Refn	RT Mirror assy w/o turn signal					0.8
13		Add for Clear Coat					0.2
14		QUARTER PANEL					
15	R&I	LT Splash guard front				0.2	
16	*	Rpr LT Quarter panel				8.0	2.4
17		Overlap Minor Panel					-0.2
18		Add for Clear Coat					0.9
19	R&I	Fuel door to 2/04/13				0.6	
20	Blnd	Fuel door to 2/04/13					0.2
21	R&I	LT Splash guard rear				0.3	
22	Repl	LT Splash guard retainer	865903S000	6	1.80		
23	*	Subl LT Quarter glass Hyundai		1	84.00 X		
24		TRUNK LID					
25	Blnd	Trunk lid					1.2
26	Repl	Nameplate "SONATA"	863103S000	1	40.30	0.2	
27	Repl	Emblem	863000Q000	1	12.84	0.2	
28	R&I	Molding				0.4	
29		REAR LAMPS					
30	R&I	RT Tail lamp assy				0.4	
31	Repl	LT Tail lamp assy	924013Q000	1	170.87	0.4	
32	R&I	RT Backup lamp assy				0.3	
33	R&I	LT Backup lamp assy				0.3	
34		REAR BUMPER					
35		O/H bumper assy				2.5	
36	R&I	R&I bumper assy				Incl.	
37	* <>	Rpr Bumper cover w/o dual exhaust				5.0	2.4
38		Overlap Major Non-Adj. Panel					-0.2
39		Add for Clear Coat					0.4
40	R&I	RT Reflector				Incl.	
41	R&I	LT Reflector				Incl.	
42	#	Repl Glass Urethane Kit		1	25.00 T		

Preliminary Estimate

Customer: Carns, Natalie

Job Number:

Vehicle: 2012 HYUN SONATA GLS 4D SED 4-2.4L-FI red

43	#	Rpr	Clean & Retape Emblems/Moldings						0.5
44	#	Rpr	D&R Battery						0.2
45	#	Rpr	Denib and Polish						1.0
46	#	Repl	Flex Additive	1		10.00	T		
47	#	Refn	Corrosion Protection						0.2
48	#	Repl	Weld-Thru Primer	1		5.00	T		
SUBTOTALS						349.81		23.0	9.1

ESTIMATE TOTALS

Category	Basis			Rate	Cost \$
Parts					309.81
Body Labor	23.0 hrs	@		\$ 50.00 /hr	1,150.00
Paint Labor	9.1 hrs	@		\$ 50.00 /hr	455.00
Paint Supplies	9.1 hrs	@		\$ 40.00 /hr	364.00
Miscellaneous					40.00
Subtotal					2,318.81
Sales Tax	\$ 629.81	@		8.3750 %	52.75
Grand Total					2,371.56
Deductible					0.00
CUSTOMER PAY					0.00
INSURANCE PAY					2,371.56

THIS ESTIMATE IS BASED ON A VISIBLE DAMAGE INSPECTION ONLY. UPON STARTING REPAIRS, THE POSSIBILITY OF HIDDEN DAMAGE MAY REQUIRE ADDITIONAL PARTS AND/OR LABOR NECESSARY TO COMPLETE THE REPAIRS.

WARNING : ANY PERSON WHO KNOWINGLY, AND WITH INTENT TO INJURE, DEFRAUD OR DECEIVE ANY INSURER, MAKES ANY CLAIM FOR THE PROCEEDS OF AN INSURANCE POLICY CONTAINING ANY FALSE, INCOMPLETE OR MISLEADING INFORMATION IS GUILTY OF A FELONY.