

427 Iowa


Condemnation





427 Iowa – East Side





427 Iowa – Chimney Close Up





427 Iowa – North Side






427 Iowa – Roof Damage





427 Iowa – Attached Garage on West Side



427 Iowa – Window on East Side





427 Iowa – Interior Living Area









427 Iowa – Storage Shed





427 Iowa - Cellar