NOTICE OF TORT CLAIM

CLAIMANT: HAC, Inc (Craig Nelson, Rich Managen Glyly filling out paper work) DATE: Glyly
ADDRESS: P.O. Box 25008 CITY: Other Okthoma City
STATE: OK ZIP: 73125 PHONE: (H) 290-3444 (W) 255-6904
DATE OF INCIDENT: JUNE 6, 2014
LOCATION OF INCIDENT: 110 ED NOBL PICKY NORMAN OK
STATEMENT OF CIRCUMSTANCES / REASONS YOU BELIEVE CITY IS LIABLE:
On GIGILY our company can was parked in the Burger King packing lot at
110 Ed Noble Parkway. It was occupied by an HAC employee, Mark
Mulkey, who was eating a sandwich - again the car was parked in a
parking space. City of Norman garbage truck for pulled in and
emptied a dumpster, then proceeded to back up quita a ways
across the lot 40 where Mark was parked - he struck marks
car before realizing he had backed so far. Mark had been them about 10
(use additional pages if necessary) Mark had been there about 10
MONETARY STATEMENT: List of expenses claimed for payment: hoppingel.
Car body repair \$ 3568.65
\$
<u> </u>
TOTAL AHOUNT CLAIMED: \$ 3,568.65
NAME AND ADDRESS OF INSURANCE COMPANY: Call me direct - Craig NElson - AGENT: 405-255-6904
AGENT: 405-255-6904
THIS FORM MUST BE SIGNED AND RETURNED WITH ALL REQUESTED INFORMATION IN ORDER TO BE PROCESSED
I SWEAR AND/OR AFFIRM THE INFORMATION PROVIDED ABOVE IS TRUE AND CORRECT.
-ILED IN THE OFFICE aris rules Director Rich Manual
OF THE CITY CLERK
ON 6-23-14 HAC, Ene.

FLAIR BODY WORKS EDMOND OK.

Workfile ID: Federal ID:

9c7e8a4c 731164358

913 S BROADWAY, EDMOND, OK 73034

Phone: (405) 330-4883 FAX: (405) 330-4889

Preliminary Estimate

RO Number: 31107

Written By: Steve Baumann

Insured:

HAC

Policy #:

Claim #:

Type of Loss:

Point of Impact:

Date of Loss:

Days to Repair:

Owner: HAC

Inspection Location:

Insurance Company:

(405) 290-3456 Business

FLAIR BODY WORKS EDMOND OK.

913 S BROADWAY **EDMOND, OK 73034**

Repair Facility

(405) 330-4883 Business

VEHICLE

Year:

Make:

Color:

2014

CHEV

IMPALA LIMITED LS

Body Style: Engine:

4D SED

6-3.6L-FI

VIN: License:

2G1WA5E38E1111150

Mileage In:

Mileage Out:

Model: Production Date: State: Dark Gray Int: Condition:

Job #:

Vehicle Out:

TRANSMISSION

Automatic Transmission

Overdrive

POWER

Power Steering

Power Brakes

Power Windows

Power Locks Power Mirrors

Power Driver Seat

DECOR

Dual Mirrors

Body Side Moldings

Tinted Glass

Console/Storage

CONVENIENCE

Air Conditioning

Intermittent Wipers

Tilt Wheel

Cruise Control

Rear Defogger

Keyless Entry

Message Center

Steering Wheel Touch Controls

RADIO

AM Radio

FM Radio

Stereo

Search/Seek

CD Player

Auxiliary Audio Connection

SAFETY

Drivers Side Air Bag

Passenger Air Bag

Anti-Lock Brakes (4)

4 Wheel Disc Brakes

Front Side Impact Air Bags

Head/Curtain Air Bags

Communications System

Hands Free Device

SEATS

Cloth Seats

Bucket Seats

WHEELS

Aluminum/Alloy Wheels

PAINT

Clear Coat Paint

OTHER

Traction Control

Stability Control

Power Trunk/Gate Release

Preliminary Estimate

RO Number: 31107

Vehicle: 2014 CHEV IMPALA LIMITED LS 4D SED 6-3.6L-FI Dark Gray

Line		Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	REAR DOOR							
2		Bind	LT Outer panel					1.0
3	*	R&I	LT Body side mldg				0.2	
4		R&I	LT Belt w'strip				0.3	
5		R&I	LT Handle, outside w/o chrome				0.3	
6		R&I	LT R&I trim panel				0.4	
7	BACK GLASS							
8		R&I	Back glass GM				Incl.	
9	PILLARS, ROC	KER &	FLOOR					
10		Repl	LT Uniside assy	89025203	1	759.70 s	25.5	6.1
11			Add for Clear Coat					2.4
12			Deduct for Rear Bumper R&I				-1.1	
13	QUARTER PAN	EL						
14		Refn	Fuel door					0.3
15			Add for Clear Coat					0.1
16		Repl	LT Wheelhouse liner	15952291	1	45.72	Incl.	
17		R&I	LT Qtr glass GM				Incl.	
18	TRUNK LID							
19		Blnd	Trunk lid w/o POLICE					1.2
20	*	R&I	Emblem				0.2	
21		Repl	Nameplate "IMPALA"	15885696	1	20.72	0.3	
22	*	R&I	Nameplate "FLEX FUEL"				0.2	
23	REAR LAMPS							
24		R&I	LT Tail lamp assy				Ind.	
25	REAR BUMPER	t						
26			O/H bumper assy				1.9	
27	*	Rpr	Bumper cover w/dual exh				4.0	3.0
28			Add for Clear Coat				_	1.2
29	**	Repl	A/M FLEX AGENT		1	5.00 T		
30	**	Repl	A/M MASK FOR OVERSPRAY		1	10.00 T		
31	#	Subl	HAZARDOUS WASTE REM.		1	5.00 X		
32	#		***POSSIBLE HIDDEN DAMAGE***		1			
				SUBTOTALS		846.14	32.2	15.3

RO Number: 31107

Vehicle: 2014 CHEV IMPALA LIMITED LS 4D SED 6-3.6L-FI Dark Gray

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$		
Parts			·	826.14	
Body Labor	32.2 hrs	@	\$ 44.00 /hr	1,416.80	
Paint Labor	15.3 hrs	@	\$ 44.00 /hr	673. 20	
Paint Supplies	15.3 hrs	@	\$ 34.00 /hr	520.2 0	
Miscellaneous				20.00	
Subtotal	<u> </u>			3,456.34	
Sales Tax	\$ 1,361.34	@	8.2500 %	112.31	
Grand Total				3,568.65	
Deductible				0.00	
CUSTOMER PAY				0.00	
INSURANCE PAY				3,568.65	

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF CRASH PARTS SU PPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHIC LE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THESE PARTS RATHER THAN THE MANUFACTURER OF YOUR VEHICLE.

WARNING: ANY PERSON WHO KNOWINGLY, AND WITH INTENT TO INJURE, DEFRAUD OR DECEIVE ANY INSURER, MAKES ANY CLAIM FOR THE PROCEEDS OF AN INSURANCE POLICY CONTAINING ANY FALSE, INCOMPLETE OR MISLEADING INFORMATION IS GUILTY OF A FELONY.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THESE PARTS RATHER THAN THE MANUFACTURER OF YOUR VEHICLE.