

CITY OF NORMAN
POST OFFICE BOX 370
NORMAN, OKLAHOMA 73070

NOTICE OF TORT CLAIM

CLAIMANT: Carmelita Burris DATE: 10/15/15
ADDRESS: 900 Schulze Dr CITY: NORMAN
STATE: OK ZIP: 73071 PHONE: (H) 405 833 1534 (W)
DATE OF INCIDENT: 10/6/15
LOCATION OF INCIDENT: SHERWOOD / Alameda

STATEMENT OF CIRCUMSTANCES / REASONS YOU BELIEVE CITY IS LIABLE:

City mower hit BACK of vehicle AT SHERWOOD
& Alameda street.

(use additional pages if necessary)

MONETARY STATEMENT: List of expenses claimed for payment:

NORMAN BODY WORKS see attachment \$ 00
David Stanley Body Shop see attachment \$ 10
Ferguson Buick GMCs see attachment \$ 00

TOTAL AMOUNT CLAIMED: \$

NAME AND ADDRESS OF INSURANCE COMPANY:

AGENT:

THIS FORM MUST BE SIGNED AND RETURNED WITH ALL REQUESTED INFORMATION IN ORDER TO BE PROCESSED

I SWEAR AND/OR AFFIRM THE INFORMATION PROVIDED IS

CORRECT.

CLAIM

FILED IN THE OFFICE
OF THE CITY CLERK
ON 10-21-15

David Stanley Body Shop
1560 24th Avenue Southwest, NORMAN, OK
73072
Phone: (405) 579-3070
FAX: (405) 579-3048

Workfile ID: c7d6cf1d
Federal ID: 46-1147591
Resale Number: 1016077505

Preliminary Estimate

Customer: BURRIS, CARMELITA

Written By: Kyle Cantrell

Insured: BURRIS, CARMELITA
Type of Loss:
Point of Impact: 06 Rear

Policy #:
Date of Loss:

Claim #: CP
Days to Repair: 8

Owner:
BURRIS, CARMELITA
900 SCHULZE DR.
NORMAN, OK 73071
(405) 833-1534 Cell

Inspection Location:
David Stanley Body Shop
1560 24th Avenue Southwest
NORMAN, OK 73072
Repair Facility
(405) 579-3070 Business

Insurance Company:
CUSTOMER PAY

VEHICLE

Year: 2011	Body Style: 4D UTV	VIN: 2CNALDEC1B6423018	Mileage In: 53783
Make: CHEV	Engine: 4-2.4L-FI	License: 109HXX	Mileage Out:
Model: EQUINOX 4X2 LT	Production Date: 4/2011	State: OK	Vehicle Out:
Color: BLUE Int:	Condition:	Job #: 1	

TRANSMISSION

Automatic Transmission
Overdrive

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Heated Mirrors

DECOR

Dual Mirrors
Privacy Glass
Console/Storage

CONVENIENCE

Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Alarm
Message Center
Steering Wheel Touch Controls
Rear Window Wiper
Telescopic Wheel

RADIO

AM Radio

FM Radio
Stereo
Search/Seek
CD Player
Auxiliary Audio Connection
Satellite Radio

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Traction Control
Stability Control
Front Side Impact Air Bags

Head/Curtain Air Bags
Communications System
Hands Free Device

ROOF

Luggage/Roof Rack

SEATS

Cloth Seats
Bucket Seats

WHEELS

Aluminum/Alloy Wheels

PAINT

Clear Coat Paint

Preliminary Estimate

Customer: BURRIS, CARMELITA

Vehicle: 2011 CHEV EQUINOX 4X2 LT 4D UTV 4-2.4L-FI BLUE

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		LIFT GATE					
2	*	Repl LKQ lift gate +25%	25959021	1	625.00	1.6	3.6
		Note: INCLUDES MLDG AND BACK CAMERA					
3		Add for Clear Coat					1.4
4		R&I Molding w/rear camera				0.2	
5	*	Repl LKQ Emblem	22760644	1	Incl.	0.2	
6		Repl RT Nameplate "EQUINOX LT"	22878313	1	25.74	0.2	
7		R&I Latch w/o power lift gate				0.3	
8	*	R&I Lift gate glass NAGS w/deep tint				1.8	
9	#	Repl URETHANE GLASS SEAL KIT		1	20.00		
10		R&I Wiper arm				0.2	
11		R&I R&I spoiler				0.3	
12		R&I Upper trim panel				0.2	
13		R&I Lower trim panel w/o power lift gate				0.4	
14		REAR BUMPER					
15	*	Rpr Bumper cover w/o reverse sensor				2.0	2.6
16		Add for Clear Coat					1.0
17		O/H bumper assy				1.8	
18		Repl Step pad	25798787	1	57.26	Incl.	
19	#	Repl Cover Car		1	5.00		
20	#	Repl Corrosion protection		1	10.00		
21	#	Hazardous Waste		1	3.00		
SUBTOTALS					746.00	9.2	8.6

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			746.00
Body Labor	9.2 hrs @	\$ 46.00 /hr	423.20
Paint Labor	8.6 hrs @	\$ 46.00 /hr	395.60
Paint Supplies	8.6 hrs @	\$ 35.00 /hr	301.00
Subtotal			1,865.80
Sales Tax	\$ 1,047.00 @	8.2500 %	86.38
Grand Total			1,952.18
Deductible			0.00
CUSTOMER PAY			0.00
INSURANCE PAY			1,952.18