





813 College Rear Building aka 813 ½ College



813 1/2 College South Elevation







813 ½ College East Elevation



813 1/2 College Stairs to Upstairs Unit







813 ½ College Close-up of West Elevation Damage








813 ½ College Upstairs Bathroom with Bird Nest in Sink





813 ½ College Hole in Roof of Upstairs Unit




813 ½ College Upstairs Unit with Buckled Flooring





813 ½ College Upstairs Missing Window and Rotted Frame



**813 ½ College Downstairs Interior  
Exterior Door Not Secured**