RRESS SHIFT-FIL TO SELECT COUNTER PRODUCTS
NORTH ORLA CITY T=14.625 S=N PU=Y AESN
NA 3/A C/A DA E/A S/A P/S B/A
H/S L/S K/N W/A V/A F/A Z/S X/N
LSB/BRS
LDW=32.99 PAI=7.00 PEP=2.95 ALI=15.72
TO USE A DEBIT CARD AT A LOCATION THAT
ACCEPTS THEM YOU ARE SUBJECT TO ADDITIONAL
CREDIT CHECKS OR MUST PRESENT ADDITIONAL
TOENTIFICATION.
MIN AGE 21. 21-24 UR SURCHARGE 4 .01DY
OTHER RESTRICTIONS MAY APPLY.
CONTACT LOCAL REPRESENTATIVE FOR DETAILS
0.50 /DY ENERGY RECOVERY FEE
\$ 10.00 EXTENSION FEE MAY APPLY.

2K MEEKLY PROMO -RENTAL IS 210 PER

4 15.98 /BY LATE RETURN FEE MAY APPLY

SAT NITE O/S REQUIRED

RATES GRP F FREE MLG MEQUIREMENTS
AVE 42.00 UNL MIN=04DY2CHR RNT
PER= 882.20 UNL MAX=0280Y
HRS= 46.75 UNL
MLS= .80

GWR= 0 SATE SUARROWITEED
GWR= 0 TOTL= 1017.97

Budget Rental Cara 6710 NW. Expressivay 720-8611

PAGE .

CUSTOMER INFORMATION	VEHICLE INFORMATION	STO	STORE LOCATION			
HOUSTON JOY 6708 LAUREL RD OKLAHOMA CITY OK 73162 (H) 405-414-1182	2016 HYUNDAI ELANTRA SEDAN 16"BASE SE/VLUE ED PLATE # UNKNOWN MILEAGE: UNKNOWN TORQUE SPECS: 080	OKO 13 2701 NW EXPRESSWAY OKLAHOMA CITY OK 73112-7047 PHONE: 405-832-9034 559 MATTHEW T HAMMOCK				
CODE CC QTY SIZE/DESCRIPTION			PRICE	AMOUNT		
32520 NRM 1 205 /55 R16 911 MCH DEFENDER	H SL BSW T + H	.00	127.00	127.00		
WARRANTY: MILEAGE- 80,000 WORKMANSH: COMMENT: BOLT PATTERN: 5-114.3 COMMENT: INFLATION F:32 R:32	IP/MATERIALS-LIFETIME ROA	D HAZARD-LI	FETIME			
80017 NRM 1 CERTIFICATES FOR REFUND, REPLACEMEN	NT	.00	18.50	18.50		
86888 NRM 1 STATE REQUIRED TIRE FEE		.00	2.90	2.90		
80219 NRM 1 INSTALLATION & LIFE OF TIRE MAINTE	ENANCE	.00	20.00	20.00		
98238 NRM 1 DIL 2020K TQ60 BLUE TPMS RBK BASIC KIT	2020K	.00	.00	- 00		
			TAX: TOTAL:	10.96 179.36		
FREE CUSTOMER FLAT REPAIR AND ROTATION This quote is good for 30 days						

FREE CUSTOMER FLAT REPAIR AND ROTATION This quote is good for 30 days THANK YOU FOR SHOPPING DISCOUNT TIRE CO.

(Salesman's Signature)

Quarter panel that was damaged rabbed On the Cutting Sidewall.



OKLAHOMA BODY WORKS INC.

6350 N ROCKWELL AVE, BETHANY, OK 73008 Phone: (405) 720-6091 FAX: (405) 720-2067

Workfile ID: PartsShare:

337343e5 5RQZrx

Federal ID: License Number:

46-1616-912 15013

Preliminary Estimate

Customer: JOY, HOUSTON Job Number:

Written By: John Bennitt

Insured:

JOY, HOUSTON

Policy #:

Date of Loss:

Claim #:

Type of Loss:

Point of Impact: 08 Left Qtr Post (Left Side)

Days to Repair: 0

Owner:

JOY, HOUSTON 6708 LAUREL RD. OKC, OK 73162 (405) 414-1182 Cell **Inspection Location:**

OKLAHOMA BODY WORKS INC.

6350 N ROCKWELL AVE BETHANY, OK 73008

Repair Facility

(405) 720-6091 Business

Insurance Company:

71,823

SELF PAY (3RD PARTY-NORMAN FIRE DEPT.)

VEHICLE

2016 HYUN Elantra SE Automatic (Alabama Plant) 4D SED 4-1.8L Gasoline MPI BLUE

VIN:

xxxxxxx9GH677024

Interior Color:

GRAY

Mileage In:

Vehicle Out:

CLR897 License:

Exterior Color:

BLUE

Mileage Out:

State:

OK

Production Date:

4/2015

Condition:

Job #:

TRANSMISSION

Automatic Transmission

POWER

Power Steering Power Brakes

Power Windows Power Locks

Power Mirrors

DECOR

Dual Mirrors Tinted Glass Console/Storage Overhead Console

CONVENIENCE

Air Conditioning

Intermittent Wipers

Tilt Wheel Cruise Control Rear Defogger

Keyless Entry

Alarm **RADIO**

AM Radio FM Radio

Stereo

Search/Seek CD Player

Auxiliary Audio Connection

Satellite Radio

SAFETY

Drivers Side Air Bag

Passenger Air Bag Anti-Lock Brakes (4)

4 Wheel Disc Brakes

Front Side Impact Air Bags Head/Curtain Air Bags

SEATS

Cloth Seats **Bucket Seats**

Reclining/Lounge Seats

WHEELS

Wheel Covers

PAINT

Clear Coat Paint

OTHER

Traction Control Stability Control

Power Trunk/Gate Release

Preliminary Estimate

Customer: JOY, HOUSTON

Job Number:

2016 HYUN Elantra SE Automatic (Alabama Plant) 4D SED 4-1.8L Gasoline MPI BLUE

Line		Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	VEHICLE DIA	GNOST	ics					
2	*	Repl	Pre-repair scan		1	m	1.0 M	
3	*	Repl	Post-repair scan		1	m	<u>1.0</u> M	
4	WHEELS	V	17/00/197 - 1-19 W - 1/00/00/00/00/00 - 191	The it does appropriate in the	19 sp40.	100	·w -w	****** VEF
5	*	R&I	LT/Rear Wheel, alloy 17"			m	0.3	
6	ROOF		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Marcon		No. Co. Co.	**	Mcccommon
7		R&I	LT Roof molding				0.6	
8	PILLARS, RO	CKER &	FLOOR			VIII.		
9		Blnd	LT Hinge pillar			s		0.8
			Note: CARRY CLEAR FROM QTR THE	ROUGH ROOF RAIL.				
10	#	Rpr	ROPE WINDSHIELD FOR REFN (LT SIDE)				0.4	
11		Blnd	LT Rocker panel			s		0.9
			Note: CARRY CLEAR FROM QTR THE	ROUGH ROCKER PANEL				
12	REAR DOOR			6/7/04-	MAX-MI			,,,
13		Blnd	LT Outer panel					1.0
14		R&I	LT W'strip on body US built				Incl.	
15		R&I	LT Belt molding w/o chrome				0.3	
16	*	R&I	LT Applique				0.2	
17		R&I	LT Regulator module US built				1.8	
18		R&I	LT Handle, outside w/o chrome				Incl.	
19		R&I	LT R&I trim panel				0.5	
20	BACK GLASS					19179 100- 111001000	*** ***	May report to be
21		R&I	Back glass Hyundai, Korea built w/o solar				Incl.	
22	#		URETHANE SEAL KIT		1	25.00		
23	QUARTER PA	NEL			***************************************			Area.
24		Repl	LT Quarter panel	715033YC00	1	1,064.11	20.0	3.2
			Note: HEMMED LIP. CANNOT REPLY	WITH RCY QTR. HAVE TO	REPL OF	M.		
25			Add for Clear Coat					1.3
26	#	Rpr	SLEEVE LT QTR PANEL				1.5	
27		Blnd	LT Tail lamp pocket					0.3
28		R&I	Fuel door				Incl.	
29		Blnd	Fuel door					0.2
30		R&I	LT Wheelhouse liner front				Incl.	
31		R&I	LT Wheelhouse liner rear				Incl.	
32		R&I	LT Deflector				Incl.	
33		R&I	LT Pressure vent				Incl.	
34		R&I	LT Applique w/o chrome				Incl.	
35		R&I	RT Mud guard				0.2	
36		R&I	LT Mud guard				Incl.	
37	*	Rpr	LT Inner qtr panel US built			S	3.0	1.0
			Note: SPOT REFN.					

Preliminary Estimate

Customer: JOY, HOUSTON						Job Number:		
016 H	YUN Elantra SE Au	utomati	c (Alabama Plant) 4D SED 4-1.8L Gasolin	e MPI BLUE				
38			Add for Clear Coat					0.2
39	#	Rpr	UNI-BODY REAR LT QTR				2.0 F	
40	REAR BODY &	FLOO	R		****	w-		2.4
41		R&I	Rear body trim US built from 11/4/10				Incl.	
42	TRUNK LID		9 · · · · · · · · · · · · · · · · · · ·	A1 +*M0004 -4000A4-	,	1000 100	9- 19019- 100	-194
43		R&I	R&I trunk lid				0.7	
44		Blnd	Trunk lid US built					1.2
45		R&I	Emblem				0.1	
46		Repl	Nameplate "ELANTRA"	863153X000	1	45.07	0.2	
47		R&I	Trunk lid trim US built				0.3	
48	REAR LAMPS			***			*****	14/4
49		R&I	RT Tail lamp assy US built w/o LED				0.3	
50		R&I	LT Tail lamp assy US built w/o LED				Incl.	
51		R&I	RT Backup lamp assy US built w/o LED				0.2	
52		R&I	LT Backup lamp assy US built w/o LED				0.2	
53	REAR BUMPER	2	777	***		700	AMERICA AND AND A STA	10)-1
54		R&I	R&I bumper assy				Incl.	
			Note: LABOR: Time is after rear body to	rim and tail lamp assem	blies are	removed.		
55	#		SEAM SEALER		1	65.00	1.0	
56	#	Repl	CHIP GUARD		1	10.00 T		1.0
57	#		COVER FOR PROTECTION		1	5.00		
58	#		CORROSION PROTECTION		1	10.00 X		
59	#		EPC		1	5.00		
			SU	BTOTALS		1,229.18	35.8	11.1

NOTES

Estimate Notes:

ESTIMATE TOTALS ARE SUBJECT TO CHANGE AFTER THE VEHICLE HAS BEEN DISASSEMBLED AND A REINSPECTION IS COMPLETED.

Prior Damage Notes:

MISCL AROUND.

Preliminary Estimate

Customer: JOY, HOUSTON

Job Number:

2016 HYUN Elantra SE Automatic (Alabama Plant) 4D SED 4-1.8L Gasoline MPI BLUE

ESTIMATE TOTALS

Category	Basis		Rate	Cost \$
Parts				1,209.18
Body Labor	31.8 hrs	@	\$ 50.00 /hr	1,590.00
Paint Labor	11.1 hrs	@	\$ 50.00 /hr	555.00
Mechanical Labor	2.0 hrs	@	\$ 95.00 /hr	190.00
Frame Labor	2.0 hrs	@	\$ 65.00 /hr	130.00
Paint Supplies	11.1 hrs	@	\$ 40.00 /hr	444.00
Body Supplies	29.1 hrs	@	\$ 2.00 /hr	58.20
Miscellaneous				20.00
Subtotal				4,196.38
Sales Tax	\$ 1,721.38	@	8.5000 %	146.32
Grand Total				4,342.70

THE ABOVE IS AN ESTIMATE BASED ON OUR INSPECTION AND DOES NOT COVE R ADDITIONAL PARTS OR LABOR WHICH MAY BE REQUIRED AFTER THE WORK H AS BEEN OPENED UP. OCCASIONALLY, AFTER WORK HAS BEEN STARTED, WORN , BROKEN, OR DAMAGED PARTS ARE DISCOVERED WHICH ARE NOT EVIDENT ON FIRST INSPECTION.

0

WARNING: ANY PERSON WHO KNOWINGLY, AND WITH INTENT TO INJURE, DEFRAUD OR DECEIVE ANY INSURER, MAKES ANY CLAIM FOR THE PROCEEDS OF AN INSURANCE POLICY CONTAINING ANY FALSE, INCOMPLETE OR MISLEADING INFORMATION IS GUILTY OF A FELONY.