

FERGUSON BUICK GMC COLLISION CENTER

Workfile ID: 33beb285
Federal ID: 730763666

www.fergusonchallenge.com
3101 BART CONNER DR, NORMAN, OK 73072
Phone: (405) 321-9777
FAX: (405) 360-9469

Estimate

RO Number:

Customer: JOHNSON, DYLAN 629 SHERWOOD DR NORMAN, OK 73071 (405) 301-0031	Insurance: CITY OF NORMAN	Adjuster: Phone: Claim: Loss Date: Deductible:	Estimator: NICK HORTON Create Date: 10/26/2017
--	------------------------------	--	---

1991 GMC Vandura G20 125" WB 2D VAN 8-5.7L Gasoline WHITE

VIN:	Interior Color:	Mileage In:	Vehicle Out:
License:	Exterior Color: WHITE	Mileage Out:	
State:	Production Date:	Condition:	Job #:

Line	Ver	Operation	Description	Qty	Extended Price \$	Part Type	Labor	Type	Paint
1	E01		SIDE PANEL						
2	E01	Repair	LT Side panel w/window w/hinged door 110"				20.0	Body	5.0
3	E01		Add for Clear Coat						2.0
4	E01	Remove/Replace	Fuel door	1	45.40T	OEM	0.3	Body	0.3
5	E01		Add for Clear Coat						0.1
6	E01	Remove/Replace	DECALS/STRIPE TAPE	1	500.00T	Other	2.0	Body	
7	E01	Refinish	ROPE GLASS						2.0
8	E01	Remove/Install	LT RUNNING BOARD				2.0	Body	
9	E01	Repair	LT RUNNING BOARD				6.0	Body	2.0
10	E01	Remove/Replace	LT RUNNING BOARD COMPONENTS	1	100.00T	Other			
11	E01		REAR LAMPS						
12	E01	Remove/Replace	LT Tail lamp	1	56.00T	A/M	0.4	Body	
13	E01	Remove/Replace	LT Side marker lamp all	1	9.00T	A/M	0.3	Body	
14	E01		REAR BUMPER						
15	E01	Remove/Replace	O/H rear bumper				1.2	Body	
16	E01	Remove/Replace	Face bar chrome	1	176.00T	A/M	0.0	Body	
17	E01	Sublet	HAZARDOUS WASTE	1	5.00	Other			
18	E01		CORROSION PROTECTION	1	10.00T	Other			
19	E01		CAR COVER	1	10.00T	Other			

Estimate Totals	Discount \$	Markup \$	Rate \$	Total Hours	Total \$
Parts					906.40
Sublet/Miscellaneous					5.00

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

Estimate

RO Number:

1991 GMC Vandura G20 125" WB 2D VAN 8-5.7L Gasoline WHITE

Labor, Body	48.00	32.2	1,545.60
Labor, Refinish	48.00	11.4	547.20
Material, Paint	38.00	11.4	433.20
Material, Shop	2.00	26.0	52.00
Subtotal			3,489.40
Sales Tax			121.77
Grand Total			3,611.17
Net Total			3,611.17

Estimate Version	Total \$
Original	3,611.17

Insurance Total \$:	3,611.17
Received from Insurance \$:	0.00
Balance due from Insurance \$:	3,611.17
Customer Total \$:	0.00
Received from Customer \$:	0.00
Balance due from Customer \$:	0.00

THIS ESTIMATE IS BASED ON OUR INSPECTION AND DOES NOT COVER ADDITIONAL PARTS OR LABOR WHICH MAY BE REQUIRED AFTER THE WORK HAS STARTED. AFTER THE WORK HAS STARTED, WORN OR DAMAGED PARTS WHICH WERE NOT EVIDENT ON FIRST INSPECTION MAY BE DISCOVERED. NATURALLY, THIS ESTIMATE CANNOT COVER SUCH CONTINGENCIES.